

## STATEMENT OF CORRECTIVE ACTION – ROYAL PRINCESS

**VESSEL:** Royal Princess  
**PORT:** Bar Harbor, ME  
**DATE:** 27<sup>TH</sup> September 2001

ITEM	REF	FINDING	ACTION TAKEN	BY WHEN (DATE)
1	07	<b>POTABLE WATER</b> INTERNATIONAL FIRE CONNECTIONS: THE INTERNATIONAL FIRE CONNECTIONS WERE NOT PROVIDED WITH REDUCED PRESSURE BACKFLOW PREVENTERS.	Corporate office technical dept to investigate / attn: PCSC.	In Progress
2	21	<b>FOOD SERVICE</b> LIDO SERVICE LINES: THERE WAS A NON-EASILY CLEANABLE GAP AT THE BASE OF THE FRYERS.	Corporate office technical dept to investigate / attn: PCSC.	In Progress
3	33	<b>HOT GALLEY</b> THE BULKHEAD AND HOOD OVER THE COMBI-OVENS DID NOT PROVIDE EASY ACCESS FOR CLEANING.	Corporate office technical dept to investigate / attn: PCSC.	In Progress
4	21	<b>FOOD SERVICE GENERAL</b> MANY OF THE GASKETS ON THE REACH IN REFRIGERATORS WERE PULLING AWAY FROM THEIR SEAL AT THE BASE OF THE DOORS.	Ventilation Officer to correct problem	To be rectified ASAP.
5	21	<b>FOOD SERVICE GENERAL</b> THE NON-FOOD CONTACT SURFACES OF OLDER FOOD PREPARATION EQUIPMENT SUCH AS RANGES, GRILLS, TILTING PANS AND BROILERS HAVE DIFFICULT TO CLEAN FEATURES.	Corporate office technical dept to investigate / attn: PCSC.	On-going
6	33	<b>FOOD SERVICE GENERAL</b> THE WALK-IN REFRIGERATORS AND FREEZERS HAD EXPOSED PIPING AND WIRING MAKING THE BULKHEADS AND DECKHEADS DIFFICULT TO CLEAN.	Corporate office technical dept to investigate / attn: PCSC.	On-going
7	20	<b>GALLEY-PASTRY AREA</b> THE BELT ON THE DOUGH SHEETER WAS FRAYED ALONG THE EDGES.	Corporate office technical dept to investigate / attn: PCSC. New Belt on Order as per Thomas Felder, Corporate Baker. Waiting to receive.	In Progress

## **STATEMENT OF CORRECTIVE ACTION – ROYAL PRINCESS**